



# KD/FD frame gasket installation

Frame




Side gaskets



For video instruction see:  
"KD\_FD gasket installation -  
side gasket.mov"

Top gasket



For video instruction see:  
"KD\_FD gasket installation -  
top gasket.mov"



|  |   |  |                                      |
|--|---|--|--------------------------------------|
|  | Contact address:<br>THERMOD AB<br>Söderborgsvägen 32<br>SE-671 95 Klässbol, Sweden<br>tel. (0)570 72 74 70<br>fax. (0)570 72 74 71<br>info@thermod.se | Drawing name:<br><b>KD/FD frame gasket<br/>         installation</b> | Drawing number:<br><b>901-002-00</b> |
|  |   | Date:<br><b>03-11-2020</b>   | Print format:<br><b>A4,A3</b>        |